


QUICK INSTALLATION GUIDE

OUTDOOR PULSE COUNTER: LAN-WMBUS-O-P(-DB)



Recommended mounting instructions:


- Mount on a solid wall using two screws
- Place the sensor 160-180cm above floor
- Mount the device with the cable gland pointing down



Step 1:

Unscrew the four screws on the front and remove the front piece so the PCB on the inside is visible.

Turn the cable gland at the bottom counterclockwise to loosen the seal. Thread the cable from the monitoring meter through the seal.



Step 2a:


Connect the cables from the meter to the terminal block according to the below. **Do NOT use the other input pins.**

Positive cable to input called PULSE_A

Negative cable to input called GROUND_A

Make sure the cables are firmly connected to the terminal block.

Put the front piece on and tighten the four screws from **Step 1**.



Step 3:

Tighten the cable gland by turning the nut clockwise. Make sure the seal is tight around the cable to prevent dust and water from entering the casing.

To activate the unit, hold a magnet on the LANSEN-label where the green arrow is pointing for 10 seconds.

Mount the device to a wall with two screws through the holes marked by green circles according to the recommended mounting instructions.

The installation is now complete!